



Deficiency Photo of the Year – 2023

Ship name:	MSC RESILIENT III
IMO Number:	9240873
Flag:	Liberia
Call sign/MMSI	D5UN9/636019443
Ship type:	Container ship
Date keel laid:	04.03.2002
Gross tonnage:	27,093
Recognized organization:	DNV AS
ISM Company:	MSC Shipmanagement Ltd (IMO No. 1535947)
Port of inspection:	Brisbane, QLD, Australia
Date of inspection:	08.02.2023
Detention:	Yes



Nature of deficiency:	Ventilators, air pipes, casings: Air pipe of no. 3 HFO tank on starboard forward wasted and holed.
Reason for winning the prize:	This picture provides a close-up view of the seriously rusted air pipe.
Photo of detainable deficiency:	Yes

Picture of the ship



Pictures of the same detainable deficiency: Ventilators, air pipes, casings



Pictures of other deficiency: Air pipe of HFO tank no. 4P forward and HFO no. 5P forward temporarily repaired with canvas bandage and painted.



Picture of other deficiency: Grey water overboard line temporarily repaired with rubber bandage in 2 locations.



Pictures of other deficiency: Section of insulation missing on the turbocharger exhaust pipe of all 4 generators





Picture of other deficiency: Fresh water generator outlet pipe temporarily repaired with doubler



Picture of other deficiency: Fresh water generator seawater inlet pipe temporarily repaired with doubler



Picture of other deficiency: Main engine jacket water cooler seawater outlet pipe temporarily repaired with doubler



Pictures of other deficiency: Cooling seawater outlet for deck machinery found leaking in 3 locations

